Release Notes Firmware Version 2.6.0

We welcome any suggestions, questions, and bug reports.
Please send your enquiries to: support@chromasens.de

Camera series: allPIXA evo 8K DXGE

Changes and new Features

- Internal refactoring
- Improvement of the internal voltage control
- Monitor the g8 training state at runtime

Bug Fixes

- Fixed bug in checking the line time for min when setting it
- Fixed the FrameActiveExtendLines bug, leading to an extra image

Errata

- LED-Flashing-Control:
    - Problems are expected when Frame Trigger and Line Trigger are off.
    - Errors are expected when exceeding the minimum sequence time
- The Internal DSNU/PRNU creation may not work properly. Please check the result is good or not.
- In Master Slave Mode there may be a constant shift between the cameras
- There may be issues with Gamma