

## Release Notes Firmware Version 2.6.0

We welcome any suggestions, questions, and bug reports.

Please send your enquiries to: [support@chromasens.de](mailto:support@chromasens.de)

**Camera series: allPIXA evo 10K 15K DXGE**

### Changes and new Features

- Internal refactoring
- Improvement of the internal voltage control

### Bug Fixes

- Fixed bug in checking the line time for min when setting it
- Fixed the FrameActiveExtendLines bug, leading to an extra image

### Errata

- LED-Flashing-Control:
  - Problems are expected when Frame Trigger and Line Trigger are off.
  - Errors are expected when exceeding the minimum sequence time
- The Internal DSNU/PRNU creation may not work properly. Please check the result is good or not.
- In Master Slave Mode there may be a constant shift between the cameras
- There may be issues with Gamma