

## Release Notes Firmware Version 2.1.2

We welcome any suggestions, questions, and bug reports.

Please send your enquiries to: [support@chromasens.de](mailto:support@chromasens.de)

**Camera series: allPIXA evo 8K CxP4**

### Changes and new Features

- CoaxPress CXP12 support!
- Added TLParamsLocked to the following features:
  - ExposureMode
  - ExposureTimeMode
  - MasterSlaveMode
  - MasterSlaveInterface
  - CxpLinkConfiguration
  - CxpVersionUsed
  - CxpConnectionTestMode
  - CxpConnectionTestPacketCountTx
  - CxpConnectionTestPacketCountRx
  - CxpConnectionTestErrorCount

### Bug Fixes

- Mono GainControl fixed (TDI was not considered correctly)
- Fixed a bug in the I2C communication
- Set the DeviceVersion also for TransportLayer Bootstrap registers
- Fixed the gamma feature bug
- Added invalidation for gain control region when the gcr parameters change (To stabilize gain control avoid working with invalid gcr values)
- Fixed a bug in LineDistance component
- Solved bugs for GCR (Gain Control Region)

### Incompatibilities

- The minimum value for "Width" feature is increased to 128

### Errata

- LED-Flashing-Control:
  - Problems are expected when TriggerMode is off.
  - Errors are expected when exceeding the minimum sequence time